SAMPLE NAME	LOCATION (GLENCAIRN)	SAMPLE DATE	SAMPLE TIME	ANALYSIS DATE	RESULTS (PPB)
GLEN 15-3	Mechanical/custodial room sink	5/7/2016	08:10:00	5/16/2016	Below Detection Limits
GLEN 15-4	Mechanical/custodial room sink	5/7/2016	08:13:00	5/16/2016	Below Detection Limits
GLEN 22-3	Girls bathroom sink - near Bean	5/7/2016	08:18:00	5/16/2016	Below Detection Limits
GLEN 22-4	Girls bathroom sink - near Bean	5/7/2016	08:21:00	5/16/2016	Below Detection Limits
GLEN 27-3	Valdespino classroom sink	5/7/2016	08:24:00	5/16/2016	Below Detection Limits
GLEN 27-4	Valdespino classroom sink	5/7/2016	08:26:00	5/16/2016	Below Detection Limits
GLEN 31-3	Foster classroom sink	5/7/2016	08:32:00	5/16/2016	1.4
GLEN 31-4	Foster classroom sink	5/7/2016	08:34:00	5/16/2016	1.2
GLEN 43-3	Tatum classroom sink	5/7/2016	08:40:00	5/16/2016	Below Detection Limits
GLEN 43-4	Tatum classroom sink	5/7/2016	08:42:00	5/16/2016	Below Detection Limits
GLEN 46-3	Nordquist classroom sink	5/7/2016	08:46:00	5/16/2016	Below Detection Limits
GLEN 46-4	Nordquist classroom sink	5/7/2016	08:48:00	5/16/2016	Below Detection Limits