SAMPLE NAME	LOCATION (MARBLE)	SAMPLE DATE	SAMPLE TIME	ANALYSIS DATE	RESULTS (PPB)
MAR 4-1	Art room sinks	5/7/2016	11:31:00	5/16/2016	2.3
MAR 4-2	Art room sinks	5/7/2016	11:31:00	5/16/2016	1.5
MAR 5-1	Art room sinks	5/7/2016	11:29:00	5/16/2016	2.4
MAR 5-2	Art room sinks	5/7/2016	11:30:00	5/16/2016	2.9
MAR 6-1	Art room sinks	5/7/2016	11:28:00	5/16/2016	Below Detection Limits
MAR 6-2	Art room sinks	5/7/2016	11:28:00	5/16/2016	Below Detection Limits
MAR 7-1	Art room sinks	5/7/2016	11:26:00	5/16/2016	Below Detection Limits
MAR 7-2	Art room sinks	5/7/2016	11:27:00	5/16/2016	Below Detection Limits
MAR 62-3	Vacant classroom sink	5/7/2016	11:39:00	5/16/2016	1.2
MAR 62-4	Vacant classroom sink	5/7/2016	11:42:00	5/16/2016	1.2
MAR 68-3	Johnson classroom sink	5/7/2016	11:46:00	5/16/2016	Below Detection Limits
MAR 68-4	Johnson classroom sink	5/7/2016	11:48:00	5/16/2016	Below Detection Limits
MAR 75-3	VanRemmen classroom bathroom sink	5/7/2016	12:03:00	5/16/2016	Below Detection Limits
MAR 75-4	VanRemmen classroom bathroom sink	5/7/2016	12:06:00	5/16/2016	Below Detection Limits
MAR 76-3	VanRemmen classroom bathroom sink	5/7/2016	11:37:00	5/16/2016	1.9
MAR 76-4	VanRemmen classroom bathroom sink	5/7/2016	11:59:00	5/16/2016	Below Detection Limits